

Flexible Mandrel for Bored

Brief description

- Flex-Mandrel

Measuring task

- measurement of diameters

Technology

- tactile
- static as well as dynamic

Special features

- flexible for different bore diameters
range of the diameters: 50-80 mm resp. 60-98 mm
- suitable for stepped holes
- only one master ring is necessary

